
9-Bit Buffer

The MC10E/100E122 is a 9-bit buffer. The device contains nine non-inverting buffer gates.

- 500ps Max. Propagation Delay
- Extended 100E VEE Range of 4.2V to 5.46 V
- 75kΩ Input Pulldown Resistors

Pinout: 28-Lead PLCC (Top View)




 * All VCC and VCCO pins are tied together on the die.

PIN NAMES


Pin	Function								
D ₀ – D ₈	Data Inputs								
Q ₀ – Q ₈	Data Outputs								

MC10E122 MC100E122

9-BIT BUFFER



LOGIC DIAGRAM



REV 2

12/93

© Motorola, Inc. 1996

DC CHARACTERISTICS (VEE = VEE(min) to VEE(max); VCC = VCCO = GND)

		0°C		25°C			85°C					
Symbol	Characteristic	min	typ	max	min	typ	max	min	typ	max	Unit	Condition
lн	Input HIGH Current			200			200			200	μΑ	
IEE	Power Supply Current										mA	
	10E		41	49		41	49		41	49		
	100E		41	49		41	49		47	57		


AC CHARACTERISTICS ($V_{EE} = V_{EE}(min)$ to $V_{EE}(max)$; $V_{CC} = V_{CCO} = GND$)

		0°C		25°C			85°C					
Symbol	Characteristic	min	typ	max	min	typ	max	min	typ	max	Unit	Condition
tPLH tPHL	Propagation Delay to Output D to Q	150	350	500	150	350	500	150	350	500	ps	
tSKEW	Within-Device Skew D to Q		75			75			75		ps	1
t _r	Rise/Fall Times 20 - 80%	300	425	800	300	425	800	300	425	800	ps	

^{1.} Within-device skew is defined as identical transitions on similar paths through a device.

MOTOROLA 2–2

OUTLINE DIMENSIONS



MC10E122 MC100E122

Motorola reserves the right to make changes without further notice to any products herein. Motorola makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Motorola assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters which may be provided in Motorola data sheets and/or specifications can and do vary in different applications and actual performance may vary over time. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. Motorola does not convey any license under its patent rights nor the rights of others. Motorola products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the Motorola product could create a situation where personal injury or death may occur. Should Buyer purchase or use Motorola products for any such unintended or unauthorized application, Buyer shall indemnify and hold Motorola and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that Motorola was negligent regarding the design or manufacture of the part. Motorola and was negligent regarding the design or manufacture of the part. Motorola and are registered trademarks of Motorola, Inc. is an Equal Opportunity/Affirmative Action Employer.

How to reach us:

USA/EUROPE/Locations Not Listed: Motorola Literature Distribution; P.O. Box 20912; Phoenix, Arizona 85036. 1–800–441–2447 or 602–303–5454

MFAX: RMFAX0@email.sps.mot.com - TOUCHTONE 602-244-6609 INTERNET: http://Design-NET.com

JAPAN: Nippon Motorola Ltd.; Tatsumi–SPD–JLDC, 6F Seibu–Butsuryu–Center, 3–14–2 Tatsumi Koto–Ku, Tokyo 135, Japan. 03–81–3521–8315

ASIA/PACIFIC: Motorola Semiconductors H.K. Ltd.; 8B Tai Ping Industrial Park, 51 Ting Kok Road, Tai Po, N.T., Hong Kong. 852–26629298





Copyright © Each Manufacturing Company.

All Datasheets cannot be modified without permission.

This datasheet has been download from:

www.AllDataSheet.com

100% Free DataSheet Search Site.

Free Download.

No Register.

Fast Search System.

www.AllDataSheet.com