



BU-00000-★
Part # color

★ 0 - Black 5 - Green
2 - Red 6 - Blue
4 - Yellow 9 - White

TEST LEADS

1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 **Page 8**



[Enlarge](#)

BU-5050-B-00-0
BNC Male-Both Ends

- Gold-plated center contact, silver-plated bodies.
- Shielded RG58C/U, MIL-C-17F, 50 ohm.
- [Product Data Sheet](#)
- [Send us your questions about this product](#)

Insulated Alligator Clips To Stackable Double Banana Plug

BU-3070-C-00-0 with RG58

BU-3070-F-00-0 with RG174

- Nickel-plated, steel; jaw opens to 5/16" (7.9 mm).
- Red (+) clips have 2" (51 mm) lead wires.
- Black (-) clips have 7" (178 mm) lead wires.
- Molded "Y" block prevents separation and corrosion.
- PVC clip insulators, (No. 62&3041).
- Nine-leaf beryllium copper, nickel-plated spring.
- Shielded RG58C/U, MIL-C-17F 50 ohm.
- Shielded RG174/U, MIL-C-17D 50 ohm.
- [Product Data Sheet](#)
- [Send us your questions about this product](#)



BU-5070-B-00-0

BNC Male TO Stackable Double Banana Plug

- Gold-plated center contact and silver-plated body.
- Nine-leaf beryllium copper, nickel-plated spring.
- Coaxial Cable: shielded RG58C/U, MIL-C-17F 50 ohm.
- Connector: MIL-C-39012 50 ohm.
- [Product Data Sheet](#)
- [Send us your questions about this product](#)

BU-5671-B-00-0

Insulated BNC To Shrouded Double Banana Plug

- 0.75" centers. Plug molded in polypropylene.
- Nine-leaf beryllium copper, nickel-plated spring.
- Insulated nylon BNC housing.
- Coaxial Cable: shielded RG58C/U, MIL-C-17F 50 ohm.
- [Product Data Sheet & Compatibility Info](#)
- [Send us your questions about this product](#)



[Contents](#)|[Next](#)

[Home](#)|[Insulated BNCs](#)|[Clips & Insulators](#)|[Insulated Test Accessories](#)

[Accessories & Probes](#)|[Kits](#)|[Cross Reference](#)

©1999-2000 Mueller Electric Company. All rights reserved.

Problems with the site should be reported to the <[a href="mailto:webmaster@muellerelectric.com?subject=Mueller Site Problem?cc=johnphillips@muellerelectric.comb" data-bbox="328 128 671 144">webmaster@muellerelectric.comb](mailto:webmaster@muellerelectric.com?subject=Mueller Site Problem?cc=johnphillips@muellerelectric.comb)>webmaster.