



# PT Series Tips for TC201T Soldering Pencil




### Screwdriver

| Cat. No. | Cat. No. | Cat. No. | A     |      | B     |      | C    |       |
|----------|----------|----------|-------|------|-------|------|------|-------|
| 600°     | 700°     | 800°     | in.   | mm   | in.   | mm   | in.  | mm    |
| PTH6     | PTH7     | PTH8     | 0.031 | 0.79 | 0.019 | 0.48 | 0.62 | 15.87 |
| PTA6     | PTA7*    | PTA8*    | 0.062 | 1.57 | 0.032 | 0.81 | 0.62 | 15.87 |
| PTB6     | PTB7*    | PTB8*    | 0.093 | 2.38 | 0.020 | 0.51 | 0.62 | 15.87 |
| PTC6     | PTC7*    | PTC8*    | 0.125 | 3.17 | 0.027 | 0.69 | 0.62 | 15.87 |
| PTD6     | PTD7     | PTD8*    | 0.187 | 4.74 | 0.035 | 0.89 | 0.62 | 15.87 |
| --       | PTE7     | PTE8     | 0.234 | 5.95 | 0.042 | 1.07 | 0.62 | 15.87 |




### Long Screwdriver

| Cat. No. | Cat. No. | Cat. No. | A     |      | B     |      | C    |       |
|----------|----------|----------|-------|------|-------|------|------|-------|
| 600°     | 700°     | 800°     | in.   | mm   | in.   | mm   | in.  | mm    |
| --       | PTJ7     | PTJ8     | 0.031 | 0.79 | 0.012 | 0.30 | 1.00 | 25.40 |
| PTKX6    | --       | --       | 0.046 | 1.17 | 0.030 | 0.76 | 1.00 | 25.40 |
| PTK6     | PTK7*    | PTK8     | 0.046 | 1.19 | 0.026 | 0.66 | 1.00 | 25.40 |
| --       | PTL7     | PTL8     | 0.078 | 1.98 | 0.027 | 0.69 | 1.00 | 25.40 |
| --       | PTM7     | PTM8     | 0.125 | 3.17 | 0.037 | 0.94 | 1.00 | 25.40 |




### Narrow Screwdriver

| Cat. No. | Cat. No. | Cat. No. | A     |      | B     |      | C    |       |
|----------|----------|----------|-------|------|-------|------|------|-------|
| 600°     | 700°     | 800°     | in.   | mm   | in.   | mm   | in.  | mm    |
| PTR6     | PTR7     | PTR8     | 0.062 | 1.58 | 0.044 | 1.12 | 0.62 | 15.87 |




### Slotted Bent

| Cat. No. | Cat. No. | Cat. No. | A     |      | B   |    | C    |       |
|----------|----------|----------|-------|------|-----|----|------|-------|
| 600°     | 700°     | 800°     | in.   | mm   | in. | mm | in.  | mm    |
| --       | PTZ7     | --       | 0.020 | 0.50 | --  | -- | 1.00 | 25.40 |




### Single Flat

| Cat. No. | Cat. No. | Cat. No. | A     |      | B     |      | C    |       |
|----------|----------|----------|-------|------|-------|------|------|-------|
| 600°     | 700°     | 800°     | in.   | mm   | in.   | mm   | in.  | mm    |
| --       | PTAA7    | PTAA8    | 0.062 | 1.57 | 0.040 | 1.42 | 0.62 | 15.87 |
| --       | PTBB7    | PTBB8    | 0.093 | 2.38 | 0.032 | 0.81 | 0.62 | 15.87 |
| --       | PTCC7    | PTCC8    | 0.125 | 3.17 | 0.032 | 0.81 | 0.62 | 15.87 |
| --       | PTDD7    | PTDD8    | 0.187 | 4.74 | 0.032 | 0.81 | 0.62 | 15.87 |




### Conical

| Cat. No. | Cat. No. | Cat. No. | A     |      | B     |      | C    |       |
|----------|----------|----------|-------|------|-------|------|------|-------|
| 600°     | 700°     | 800°     | in.   | mm   | in.   | mm   | in.  | mm    |
| --       | --       | PTT8     | 0.025 | 0.63 | 0.036 | 0.91 | 0.62 | 15.87 |
| PTP6     | PTP7*    | PTP8*    | 0.031 | 0.79 | 0.012 | 0.30 | 0.62 | 15.87 |



### Long Conical

| Cat. No. | Cat. No. | Cat. No. | A     |      | B     |      | C    |       |
|----------|----------|----------|-------|------|-------|------|------|-------|
| 600°     | 700°     | 800°     | in.   | mm   | in.   | mm   | in.  | mm    |
| PTS6     | PTS7     | PTS8     | 0.015 | 0.39 | --    | --   | 1.00 | 25.40 |
| PTO6     | PTO7*    | PTO8*    | 0.031 | 0.79 | 0.044 | 1.12 | 1.00 | 25.40 |



### Conical Flat

| Cat. No. | Cat. No. | Cat. No. | A     |      | B     |      | C    |       |
|----------|----------|----------|-------|------|-------|------|------|-------|
| 600°     | 700°     | 800°     | in.   | mm   | in.   | mm   | in.  | mm    |
| --       | PTF7     | PTF8     | 0.047 | 1.19 | 0.033 | 0.84 | 0.62 | 15.87 |

\* Indicates available bulk (100 multiples only)