

Addendum to
MC145574EVK/D Rev. 1.0
ISDN S/T-Interface Transceiver Evaluation Kit

March 24, 1999

This addendum applies to the following sections of MC145574EVK/D, Rev. 1.0:

- Appendix A, MC145574EVK Electrical Board Schematic (Analog Part of the Board)

The following pages have been amended. Please take the time to make a permanent note of these changes in your book. Updates are also posted at the Motorola ISDN web site: www.motorola.com/isdn-chips

Appendix A, MC145574EVK Electrical Board Schematic (Analog Part of the Board)

Page:

5-1 The RJ45 pinout connection on RJ45 (NTST1 and NTST2) is not compliant. The following table shows the pins as they should be:

Pin Number	As Currently Shown	Correct Pinout
Pin 1	NC	NC
Pin 2	NC	NC
Pin 3	RxP	RxP
Pin 4	TxN	TxP
Pin 5	TxP	TxN
Pin 6	RxN	RxN
Pin 7	NC	NC
Pin 8	NC	NC

[查询"MC145574EVKAD"供应商](#)