



586 SERIES

LED Replacement Lamps

Single Contact Bayonet Base



FEATURES / BENEFITS

- ▲ Reduced current draw vs. incandescent
- ▲ Reduced maintenance
- ▲ Long life reliable reading light
- ▲ Addresses No. 1 passenger complaint: Lamp failure

APPLICATION

12 Volt Blue LED Lamp

586-4605-802


- Interior low level coach lighting
- Under seat mounted aisle path lighting
- Replaces incandescent lamps on MCI and Prevost Coaches

24 Volt White Reading Light

586-4606-801

- Incandescent bulb replacement
- Designed for MCI reading lamp assembly
- Fits Coach models 102D/DL, D4000, and D4500

SPECIFICATIONS



Part Number	Color	Operating Voltage	Typical Current	Intensity
586-4605-802	Blue	12 V	60 mA	7000 mcd
586-4606-801	White	24 V	55 mA	46000 mcd



A4703



Dialight Corporation

ISO 9001

Dialight Corporation

1501 Route 34 South • Farmingdale, NJ 07727 USA
 Tel: (1) 732.919.3119 • Fax: (1) 732.751.5778 • www.dialight.com



a Roxboro Group Company

MDTB586X001_A